



68-013-02 Prince George's Bank

3800 34th Street

Mount Rainier

Built in 1922, Prince George's Bank (Mount Rainier branch) is a brick building of irregular plan conforming to its corner location; entrance is through a classical portico with Tuscan style columns. The building is distinguished by a ten-sided cupola with round-arch, multipane windows and ten-plane pyramidal roof. Designed by architect Frank Elmer Hill of Washington, D.C., the bank was built as a branch of the Prince George's Bank established in Hyattsville in 1915. The building is an important example of an early twentieth-century suburban commercial structure, with a neoclassical design typical of prominent financial institutions.