


Livingston Woods Pond and Stream Restoration



Legend for Livingston Woods Pond and Stream Restoration

Property

Road Casings




Property




Environmental


Stream Center and Drainage (2020)




Bulkhead




Dam




Drainage Connector




Floodwall




Headwall




Hidden Single Line Stream




Hidden Stream Poly Centerlines




Hidden Water Canal




Hidden Water Cooling Channel




Single Line Stream




Stream Poly Centerlines




Water Canal



Water Cooling Channel



Potential Forested Interior Dwelling Specie (DNR)



Sensitive Species Review (DNR)



Tier II Catchment (MDE)



Tier II Stream Segment (MDE)



Latest Imagery

2023 Color (May) - 3 inch

Image



Red: Band_1



Green: Band_2



Blue: Band_3

Default

Property Base Fill

